

U.S. Department of Transportation

1200 New Jersey Avenue, SE. Washington, DC 20590

National Highway Traffic Safety Administration

June 6, 2008

MR. JAN URBAHN
GENERAL MANAGER, SAFETY ENGINEERING
AND INTELLIGENT TRANSPORTATION SYSTEMS
BMW OF NORTH AMERICA, LLC
PO BOX 1227
WESTWOOD, NJ 07675-1227

NVS-215dgl 08V-254

Subject: FRONT BRAKE LINES

Dear MR. URBAHN:

This letter serves to acknowledge BMW of North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety defect in the products described below, for which a safety recall campaign shall be conducted pursuant to 49 U.S.C. § 30119.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/R1200 GS/2006-2007 BMW/R1200 R/2007-2008 BMW/R1200 ST/2007

NHTSA Campaign Number: 08V-254 Mfg's Report Date: May 27, 2008

Components: SERVICE BRAKES, HYDRAULIC: FOUNDATION COMPONENTS:

HOSES, PIPING/LINES, FITTINGS

Potential Number of Units Affected: 3,248

Summary:

BMW IS RECALLING 3,248 MY 2007-2008 R1200R, MY 2006-2007 R1200 GS AND MY 2007 R1200 ST MOTORCYCLES. DUE TO THE CURRENT ROUTING OF THE FRONT BRAKE LINES, IT IS POSSIBLE THAT DURING RIDING, THE BRAKE LINES COULD BE UNDER STRAIN. IF THE VIBRATION/STRAIN IS SIGNIFICANT, THE BRAKE LINES COULD SPLIT AND START TO DEVELOP A LEAK. IF THE LEAK BECAME SIGNIFICANT, BRAKE FLUID COULD ESCAPE. IF THIS HAPPENED, THE LEVEL OF FLUID IN THE RESERVOIR OF THE FRONT BRAKE SYSTEM COULD DROP.

Consequence:

IF FLUID LEVEL DROPS SIGNIFICANTLY, THE FRONT BRAKES COULD FAIL INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL INSPECT AND INSTALL NEW BRAKE LINES WITH A MODIFIED ROUTING FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING JUNE 2008. OWNERS MAY CONTACT BMW AT 1-800-831-1117.

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO http://www.safercar.gov.

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

We have reviewed your proposed owner notification letter and it meets the requirements of Part 577.

Please provide the following additional information and be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after the close of the calendar quarter.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at Patricia.wallace@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

George H. Person

Chief, Recall Management Division

Office of Defects Investigation

Patricia Wallace for

Enforcement